

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

AT230  
SSE  
1/4-1/2  
0.352 mi.  
1858 ft.  
VAULT#1532  
WEST 8TH & SURF AVE  
BROOKLYN, NY  
Site 1 of 10 in cluster AT

NY Spills S106866809  
N/A

Relative:  
Higher

Actual:  
3 ft.

SPILLS:

Name: VAULT#1532  
Address: WEST 8TH & SURF AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0412478 / 2006-01-05  
Facility ID: 0412478  
Facility Type: ER  
DER Facility ID: 273294  
Site ID: 337961  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2005-02-24  
Investigator: JHOCONE  
Referred To: Not reported  
Reported to Dept: 2005-02-24  
CID: 444  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2005-02-24  
Spill Record Last Update: 2006-01-05  
Spiller Name: ERT DESK  
Spiller Company: VAULT#1532  
Spiller Address: WEST 8TH & SURF AVE  
Spiller Company: 001  
Contact Name: ERT DESK  
DEC Memo: "e2mis no. 157366: 2/24/05 - 1003hrs - Erik Loadholt # 81970 Mech B Networks reports 2 gallons transformer oil leaked from phase 1 bushing on side of VS1532 and spilled onto leaves and dirt on concrete floor of structure. No sewers or waterways appear to be affected. Upon arrival found sump pump disconnected. When the Supv Teresa Haering arrives she will check pump to assure that there was no escape of oil. Loadholt relieved pressure from unit and leak has stopped. Unit is below min. Pressure test will not be done. Sample taken from unit marked E priority. Clean up pending safe access and sample results. UPDATE 2/24/05 10:55 HRS... THIS IS ON FDR 11B04.. HISTORIC SHOWS 0 PPM FROM 6/23/2003 AND THE UNIT WAS LAST PRESSURE TESTED AND HELD PRESSURE ON 1/10/2005. Update - 1100hrs - E. Loadholt reports bushing is still leaking at a rate of 1 drop every 10 min. UPDATE: 2/24/05 - 1400 G. PALLADINO - O.S. - B.Q.E., REPORTS LEAK HAS GOTTEN WORSE. UNIT TO BE DRAINED AS 50 - 499 AS SOON AS POSSIBLE. EPA # ISSUED 2/24/05 - 1420. NYP 004 129 094. OVER 50 TANKER ORDERED. UPDATE: 2/24/05 - 1547 T. HARING - O.S. - BQE, REPORTS THAT THE UNIT IS APPROX 15 GALS BELOW MIN. APPROX 14 OF THESE 15 GALS IS IN THE STRUCTURE. 1/2 GAL OF THE DIEL FLUID WAS FOUND IN THE CEMENT SUMP AND APPROX 1 QT WAS FOUND IN THE TRAP. THAT LEAVES APPROX 1 QT OF DIEL

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

FLUID THAT WENT THROUGH THE TRAP AND INTO THE SEWER SYSTEM. UPDATE  
2/24/05 19:25 HRS SAMPLE DELIVERED TO CHEM LAB BY COURIER. UPDATE  
2/24/05 21:45 HRS BQE E. LOADHOLT #81970 REPORTS AT THIS TIME THE  
TANKER DRAINED 485 GALS FROM THE UNIT WHICH HOLDS 497 GALS. THE UNIT  
IS STILL IN THE GROUND, AND NO AGENCIES CAME TO LOCATION. Lab  
Sequence Number: 05-01665-001 Date Approved: 2/24/2005 Total PCB <1  
PPM UPDATE: 6/28/2005 11:50 Guy Palladino reports scaffolding over  
structure. Transformer removal pending scaffold removal. 10/14/2005  
19:05 HRS. -- J. CUADRADO OF BROOKLYN ENV OPS REPORTS EQUIPMENT GROUP  
REMOVED TRANSFORMER, THEN ENV OPS DOUBLE WASHED STRUCTURE WITH BIOGEN  
760, REMOVED LIQUIDS AND SOLIDS WITH VACTOR, FOUND NO SUMPS OF  
DRAINS, AND REMOVED ENV STOP TAG 36637. CLEANUP COMPLETE AT THIS  
TIME. 10/14/2005 20:55 HRS. -- P. SELEDTSOV #19936 OF EQUIPMENT GROUP  
REPORTS OLD TRANSFORMER WAS REMOVED AND NEW TRANSFORMER INSTALLED."  
"CONED # 157366: NO TO 5 QUESTIONS:"

Remarks:

All Materials:

Site ID: 337961  
Operable Unit ID: 1099970  
Operable Unit: 01  
Material ID: 580245  
Material Code: 0020A  
Material Name: transformer oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 2.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported